



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Pate	nt of:)	
КЕІЈІ КО	OMOTO ET AL.	:	Examiner: Janis L. Dote
Appln. No	o.: 09/987,490	:	Art Unit: 1756
Filed: No	ovember 15, 2001	;)	SEP SEP
	IMAGE FORMING METHOD AND APPARATUS	;) ;)	Certificate of Correction
U.S. Pate	nt No.: 7,043,175 B2	:	
Issued: 1	May 9, 2006)	September 21, 2006

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

09/25/2026 90ENDOB1 00020088 7048175 01 F0:1811 102.03 09 Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Peter Saxon

Attorney for Patentees Registration No. 24,947

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY_Main 591726v1

PATENT NO. :

US 7,043,175 B2

DATED

May 9, 2006

INVENTOR(S) :

KEIJI KOMOTO ET AL.

Page 1 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE [56] REFERENCES CITED:

U.S. Patent Documents, "5,840,755 A 11/1998 Liedtke" should read --5,480,755 A 1/1996 Uchiyama et al.--.

ON THE TITLE PAGE [56] REFERENCES CITED:

Foreign Patent Documents, "FOREIGN PATENT DOCUMENTS" should read

JP	54-086341	7/1979
JP	55-18656	2/1980
JP	56-142540	11/1981
JP	57-151952	9/1982
JP	59-168458	9/1984
JP	59-200254	11/1984
JР	59-200256	11/1984
JP	59-200257	11/1984
JР	59-224102	12/1984
JP	60-3181	1/1985
JP	60-12554	1/1985
JP	60-69660	4/1985
JP	61-141452	6/1986
JP	61-249059	11/1986
JP	61-275864	12/1986
JP	62-258472	11/1987
JP	63-149669	6/1988
JP	63-250660	10/1988

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_Main 591726v1 PATENT NO. _US 7,043,175 B2

No. of add'l. copies @ 30¢ per page





PATENT NO. :

US 7,043,175 B2

DATED

May 9, 2006

INVENTOR(S) :

KEIJI KOMOTO ET AL.

Page 2 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

JP	2-111962	4/1990
JP	2-120865	5/1990
JP	4-9860	1/1992
JP	4-264453	9/1992
JP	5-66608	3/1993
JP	5-150539	6/1993
JP	5-346682	12/1993
JP	7-99442	10/1995
JP	10-239897	9/1998
JP	10-307421	11/1998
JP	10-307455	11/1998
JP	10-307456	11/1998
JP	10-307457	11/1998
JP	10-307458	11/1998

COLUMN 2:

Line 10, "uses," should read --use,--.

COLUMN 3:

Line 62, "mechanism" should read --mechanisms--.

COLUMN 5:

Line 41, "to" should read --to be--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)


NY_Main 591726v1

PATENT NO. <u>US 7,043,175 B2</u>

No. of add'l. copies @ 30¢ per page

2 8 20051





PATENT NO. :

US 7,043,175 B2

DATED

May 9, 2006

INVENTOR(S) :

KEIJI KOMOTO ET AL.

Page 3 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10:

Line 36, "then" should read --than--; and Line 47, "bond's" should read --bonds--.

COLUMN 11:

Line 25, "member," should read --member--; and Line 31, "image-bearing" should read --image-bearing--.

COLUMN 13:

Line 7, "particles)," should read --particles,--.

COLUMN 20:

Line 32, "Fischer-Tiropsch" should read --Fischer-Tropsch--.

COLUMN 21:

Line 57, "3-28 m 1 /g," should read --3-28 m 2 /g,--.

COLUMN 24:

Line 27, "photographic" should read --photographed--;

Line 49, "is" should read --is from the--;

Line 50, "apparatus" should read --apparatus and--;

Line 51, "avid" should read --avoid--; and

Line 64, "recover" should read --recovery--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_Main 591726v1 PATENT NO. <u>US 7,043,175 B2</u>

No. of add'l. copies @ 30¢ per page





PATENT NO.

US 7,043,175 B2

DATED

May 9, 2006

INVENTOR(S) :

KEIJI KOMOTO ET AL.

Page 4 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 30:

Line 21, "due" should read --due to--.

COLUMN 31:

Line 6, "it" should read --it is--;

Line 18, "10-200,000 mm²/d," should read --10-200,000mm²/sec,--;

Line 19, "S." should read --sec.--; and

Line 22, "200,000 mm/sec," should read --200,000mm²/sec,--.

COLUMN 32:

Line 44, "a" should read --an--.

COLUMN 33:

Line 45, "using a" should read --using--; and

Line 56, "an" should read -- and --.

COLUMN 35:

Line 35, "image-baring" should read --image-bearing--; and

Line 63, "image-baring" should read --image-bearing--.

COLUMN 36:

Line 19, "image bearing" should read --image-bearing--; and

Line 66, "react" should read --react to--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. <u>US 7,043,175 B2</u>

No. of add'l. copies @ 30¢ per page

P 2 8 2006

Stable Ould Stable PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. :

US 7,043,175 B2

DATED

May 9, 2006

INVENTOR(S) :

KEIJI KOMOTO ET AL.

Page 5 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 39:

Line 13, "sing" should read --using--;

Line 17, "added" should read --added with--;

Line 24, "Coulter counter" should read -- COULTER COUNTER--;

Line 47, "Preferring" should read --Referring--; and

Line 51, "30b" should read --308b--.

COLUMN 42:

Line 13, "charting" should read --charging--.

COLUMN 44:

Line 10, "a" should be deleted.

COLUMN 46:

Line 66, "voltage, wave-" should read --voltage wave---.

COLUMN 47:

Line 22, "constraint" should read --constrained--; and

Line 48, "saturatio" should read --saturation--.

COLUMN 48:

Line 15, "preferred" should read --preferred to--; and

Line 51, "an" should read --a--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801


(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. US 7,043,175 B2

No. of add'l. copies @ 30¢ per page

23 200



PATENT NO.

US 7,043,175 B2

DATED

May 9, 2006

INVENTOR(S) :

KEIJI KOMOTO ET AL.

Page 6 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 49:

Line 23, "polychloroifluoroethylene," should read

--polychlorofluoroethylene,--;

Line 28, "ironically" should read --ionically--; and

Line 65, "injection-barier" should read --injection-barrier--.

COLUMN 52:

Line 42, "bismuth," should read --bismuth (Bi),--; and

Line 65, "PI3;" should read --PI3;--.

COLUMN 53:

Line 41, "halogen (X" should read --halogen (X)--.

COLUMN 54:

Line 3, "becomes possible" should read --becomes--; and

Line 46, "possible" should read --possible to--.

COLUMN 56:

Line 25, "may" should read --may be--;

Line 52, "may be" should read --may--; and

Line 63, "point" should read --points--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_Main 591726v1 PATENT NO. <u>US 7,043,175 B2</u>

No. of add'l. copies @ 30¢ per page

3 2000



PATENT NO.

US 7,043,175 B2

DATED

May 9, 2006

INVENTOR(S) :

KEIJI KOMOTO ET AL.

Page 7 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 57:

Line 40, "2" should be deleted; and

Line 53, "at center line" should read --as center line--.

COLUMN 58:

Line 22, "vinyl resin" should read --vinyl resin,--;

Line 27, "an" should read --and--;

Line 41, "10-6 ohm.cm," should read --106 ohm.cm,--; and

Line 42,"10-6 ohm.cm." should read --106 ohm.cm.--.

COLUMN 59:

Line 6, "formula]" should read --formula:--;

Line 29, "power" should read --powder--;

Line 38, "fol-" should be deleted;

Line 39, "lowability" should read --flowability--; and

Line 51, "be" should be deleted.

COLUMN 60:

Line 1, "collapsion" should read -- the collapse--; and

Line 63, "(clearless" should read --(cleanerless--.

COLUMN 62:

Line 47, "member 1," should read --member 1,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

SSP 28 200

No. of add'l, copies

@ 30¢ per page

PATENT NO. US 7,043,175 B2

PATENT NO.

US 7,043,175 B2

DATED

May 9, 2006

DATED

1v1u_j 5, 2000

INVENTOR(S): KEIJI KOMOTO ET AL.

Page 8 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 63:

Line 52, "ozonless-type" should read --ozoneless-type--.

COLUMN 64:

Line 64, "causitic" should read -- caustic--.

COLUMN 65:

Line 5, "power 1." should read --powder 1.--;

Line 56, "wax" should read --was--; and

Line 61, "power 1." should read --powder 1.--.

COLUMN 66:

Line 46, " $(\ge 5\mu m)$ " should read -- $(D \ge 5\mu m)$ --; and

Line 47, "Rs 100 ohm.cm," should read --Rs=100 ohm.cm,--.

COLUMN 68:

Line 15, "(monoazodye" should read -- (monoazo dye--; and

Line 38, "Toner 13)" should read --Toner 13>--.

COLUMN 71:

Line 22, "1pm" should read --1µm--; and

Line 60, "(105 14Hz)" should read --(105 MHz)--.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 7,043,175 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

्राह्म स्ट्रिक्ट्रिक्ट्रिक



No. of add'l. copies

@ 30¢ per page

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 7,043,175 B2

DATED

May 9, 2006

INVENTOR(S) :

KEIJI KOMOTO ET AL.

Page 9 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 74:

Line 14, "-400 vols" should read ---400 volts--;

Line 37, "bis" should read --bias--; and

Line 58, "aral" should read -- areal--.

COLUMN 75:

Line 6, " \ge < 1.00" should read --< 1.00--.

COLUMN 77:

Line VA_c=0.5, "" should read --Vac=0.5--.

COLUMN 78:

Table 3, "Intial" should read --Initial--.

COLUMN 79:

Table 3, "Intial" should read --Initial--; "46" (in Example 13) should read --45--; and "O" (in comp. g) should read --D--..

COLUMN 82:

Table 4, "Px103" should read --Px104--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3801 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_Main 591726v1 PATENT NO. <u>US 7,043,175 B2</u>

No. of add'l. copies @ 30¢ per page

~ 3 8 200**6**.



Stable Here Ould!

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

US 7,043,175 B2

DATED

May 9, 2006

KEIJI KOMOTO ET AL.

Page 10 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 84:

INVENTOR(S) :

Line 33, "image bearing" should read --image-bearing--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_Main 591726v1

PATENT NO. <u>US 7,043,175 B2</u>

No. of add'l. copies @ 30¢ per page





Staple Here Here PRINTER'S TRIM Only!

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO. :

INVENTOR(S) :

US 7,043,175 B2

DATED

May 9, 2006

KEIJI KOMOTO ET AL.

Page 1 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE [56] REFERENCES CITED:

U.S. Patent Documents, "5,840,755 A 11/1998 Liedtke" should read --5,480,755 A 1/1996 Uchiyama et al.--.

ON THE TITLE PAGE [56] REFERENCES CITED:

Foreign Patent Documents, "FOREIGN PATENT DOCUMENTS" should read

JP	54-086341	7/1979
JP	55-18656	2/1980
JP	56-142540	11/1981
JP	57-151952	9/1982
JP	59-168458	9/1984
JP	59-200254	11/1984
JP	59-200256	11/1984
JP	59-200257	11/1984
JP	59-224102	12/1984
JP	60-3181	1/1985
JP	60-12554	1/1985
JP	60-69660	4/1985
JP	61-141452	6/1986
JP	61-249059	11/1986
JP	61-275864	12/1986
JP	62-258472	11/1987
JP	63-149669	6/1988
JP	63-250660	10/1988

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile



No. of add'l. copies

@ 30¢ per page

PATENT NO. US 7,043,175 B2

PATENT NO. :

US 7,043,175 B2

DATED

May 9, 2006

INVENTOR(S) :

KEIJI KOMOTO ET AL.

Page 2 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

JP	2-111962	4/1990
JP	2-120865	5/1990
JP	4-9860	1/1992
JP	4-264453	9/1992
JP	5-66608	3/1993
JP	5-150539	6/1993
JP	5-346682	12/1993
JP	7-99442	10/1995
JP	10-239897	9/1998
JP	10-307421	11/1998
JP	10-307455	11/1998
JP	10-307456	11/1998
JP	10-307457	11/1998
JP	10-307458	11/1998

COLUMN 2:

Line 10, "uses," should read --use,--.

COLUMN 3:

Line 62, "mechanism" should read --mechanisms--.

COLUMN 5:

Line 41, "to" should read --to be--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>US 7,043,175 B2</u>

No. of add'i. copies @ 30¢ per page

 \Rightarrow

PATENT NO.

US 7,043,175 B2

DATED

May 9, 2006

INVENTOR(S) :

KEIJI KOMOTO ET AL.

Page 3 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10:

Line 36, "then" should read --than--; and

Line 47, "bond's" should read --bonds--.

COLUMN 11:

Line 25, "member," should read --member--; and

Line 31, "image-bearing" should read --image-bearing--.

COLUMN 13:

Line 7, "particles)," should read --particles,--.

COLUMN 20:

Line 32, "Fischer-Tiropsch" should read -- Fischer-Tropsch--.

COLUMN 21:

Line 57, "3-28 m 1 /g," should read --3-28 m 2 /g,--.

COLUMN 24:

Line 27, "photographic" should read --photographed--:

Line 49, "is" should read --is from the--;

Line 50, "apparatus" should read --apparatus and--;

Line 51, "avid" should read --avoid--; and

Line 64, "recover" should read --recovery--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. <u>US 7,043,175 B2</u>

No. of add'l. copies @ 30¢ per page



PATENT NO.

US 7,043,175 B2

DATED

May 9, 2006

INVENTOR(S) :

KEIJI KOMOTO ET AL.

Page 4 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 30:

Line 21, "due" should read --due to--.

COLUMN 31:

Line 6, "it" should read --it is--;

Line 18, "10-200,000 mm ²/d," should read --10-200,000mm²/sec,--;

Line 19, "S." should read --sec .--; and

Line 22, "200,000 mm/sec," should read --200,000mm²/sec,--.

COLUMN 32:

Line 44, "a" should read --an--.

COLUMN 33:

Line 45, "using a" should read --using--; and Line 56, "an" should read --and--.

COLUMN 35:

Line 35, "image-baring" should read --image-bearing--; and Line 63, "image-baring" should read --image-bearing--.


COLUMN 36:

Line 19, "image bearing" should read --image-bearing--; and Line 66, "react" should read --react to--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>US 7,043,175 B2</u>

No. of add'l. copies @ 30¢ per page





PATENT NO.

US 7,043,175 B2

DATED

May 9, 2006

INVENTOR(S) :

KEIJI KOMOTO ET AL.

Page 5 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 39:

Line 13, "sing" should read --using--;

Line 17, "added" should read --added with--;

Line 24, "Coulter counter" should read -- COULTER COUNTER--;

Line 47, "Preferring" should read -- Referring--; and

Line 51, "30b" should read --308b--.

COLUMN 42:

Line 13, "charting" should read --charging--.

COLUMN 44:

Line 10, "a" should be deleted.

COLUMN 46:

Line 66, "voltage, wave-" should read --voltage wave---.

COLUMN 47:

Line 22, "constraint" should read --constrained--; and

Line 48, "saturatio" should read --saturation--.

COLUMN 48:

Line 15, "preferred" should read --preferred to--; and

Line 51, "an" should read --a--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_Main 591726v1 PATENT NO. <u>US 7,043,175 B2</u>

No. of add'l. copies @ 30¢ per page

__>

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

US 7,043,175 B2

DATED

May 9, 2006

KEIJI KOMOTO ET AL.

Page 6 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 49:

INVENTOR(S) :

Line 23, "polychloroifluoroethylene," should read --polychlorofluoroethylene,--;

Line 28, "ironically" should read --ionically--; and

Line 65, "injection-barrier" should read --injection-barrier--.

COLUMN 52:

Line 42, "bismuth," should read --bismuth (Bi),--; and Line 65, "PI3;" should read --PI3;--.

COLUMN 53:

Line 41, "halogen (X" should read --halogen (X)--.

COLUMN 54:

Line 3, "becomes possible" should read --becomes--; and Line 46, "possible" should read --possible to--.

COLUMN 56:

Line 25, "may" should read --may be--; Line 52, "may be" should read --may--; and Line 63, "point" should read --points--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies

PATENT NO. <u>US 7,043,175 B2</u>

@ 30¢ per page

⇒ _

PATENT NO. :

US 7,043,175 B2

DATED

May 9, 2006

INVENTOR(S) :

KEIJI KOMOTO ET AL.

Page 7 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 57:

Line 40, "2" should be deleted; and

Line 53, "at center line" should read --as center line--.

COLUMN 58:

Line 22, "vinyl resin" should read --vinyl resin,--;

Line 27, "an" should read --and--;

Line 41, "10-6 ohm.cm," should read --106 ohm.cm,--; and

Line 42,"10⁻⁶ ohm.cm." should read --10⁶ ohm.cm.--.

COLUMN 59:

Line 6, "formula]" should read --formula:--;

Line 29, "power" should read --powder--;

Line 38, "fol-" should be deleted;

Line 39, "lowability" should read --flowability--; and

Line 51, "be" should be deleted.

COLUMN 60:

Line 1, "collapsion" should read --the collapse--; and

Line 63, "(clearless" should read --(cleanerless--.

COLUMN 62:

Line 47, "member 1," should read --member 1,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. <u>US 7,043,175 B2</u>

No. of add'l. copies @ 30¢ per page

多类 复元 打

⇒ _

PATENT NO. :

US 7,043,175 B2

DATED

May 9, 2006

INVENTOR(S) :

KEIJI KOMOTO ET AL.

Page 8 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 63:

Line 52, "ozonless-type" should read --ozoneless-type--.

COLUMN 64:

Line 64, "causitic" should read --caustic--.

COLUMN 65:

Line 5, "power 1." should read --powder 1.--; Line 56, "wax" should read --was--; and Line 61, "power 1." should read --powder 1.--.

COLUMN 66:

Line 46, " $(\ge 5\mu m)$ " should read -- $(D \ge 5\mu m)$ --; and Line 47, "Rs 100 ohm.cm," should read --Rs=100 ohm.cm,--.

COLUMN 68:

Line 15, "(monoazodye" should read --(monoazo dye--; and Line 38, "Toner 13)" should read --Toner 13>--.

COLUMN 71:

Line 22, "1pm" should read --1 \mum--; and Line 60, "(105 14Hz)" should read --(105 MHz)--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

(212) 218-2200 -

No. of add'l. copies @ 30¢ per page

júč,

PATENT NO. US 7,043,175 B2

PRINTER'S TRIM LINE Staple Here Onlyl

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. :

US 7,043,175 B2

DATED

May 9, 2006

INVENTOR(S) :

KEIJI KOMOTO ET AL.

Page 9 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 74:

Line 14, "-400 vols" should read ---400 volts--;

Line 37, "bis" should read --bias--; and

Line 58, "aral" should read --areal--.

COLUMN 75:

Line 6, " \geq < 1.00" should read --< 1.00--.

COLUMN 77:

Line VA_c=0.5, "" should read --Vac=0.5--.

COLUMN 78:

Table 3, "Intial" should read -- Initial--.

COLUMN 79:

Table 3, "Intial" should read --Initial--; "46" (in Example 13) should read --45--; and "O" (in comp. g) should read --D--..

COLUMN 82:

Table 4, "Px103" should read --Px104--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

NY Main 591726v1

PATENT NO. <u>US 7,043,175</u> B2

No. of add'l. copies @ 30¢ per page

SEP 2 8 2006 ⇒ ____

PRINTER'S TRIM LINE Staple Here Onlyl

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

US 7,043,175 B2

DATED

May 9, 2006

INVENTOR(S) :

KEIJI KOMOTO ET AL.

Page 10 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 84:

Line 33, "image bearing" should read --image-bearing--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

NY_Main 591726v1

PATENT NO. <u>US 7,043,175 B2</u>

No. of add'l. copies @ 30¢ per page

